

Question/Issue

(Ribbon bar) Even when the ribbon bar is active, many of the individual buttons are inactive (grayed out). Why?

Answer/Solution

They are only active when Mastercam is ready to make selections. Only the buttons that are useful and relevant to the current function are active. For example, if there are no solids in your part, the buttons for selecting solids will be grayed out.