

Question / Issue



Error opening c:\.....hsttoolpathko.tmp

Answer / Solution


Problem: user gets the following error when trying to generate a HST toolpath. "Error opening c:\.....hsttoolpathko.tmp

Cause: The error should read "Unable to determine a valid machining zone - no toolpath created". However with Multi-threading enabled under Settings, Configuration, Toolpaths, you will get this error instead.

Example error messages with Multi-threading enabled



Example error message with Multi-threading disabled



Solution: Correct toolpath as you would anytime you get the "Unable to determine a valid machining zone"